



Mutual Fifty-Nine

RECOMMENDED ANGLE STOP REPLACEMENT

Due to failures of a one piece angle stop/water supply line causing considerable damage because of water leaks, Mutual 59 is strongly recommending immediate replacement with a two piece set up of angle stops and braided stainless steel water supply lines.



Old Single-piece angle stop

Stainless steel braided angle stop

Mutual 59 will inspect to see that these replacements have been made by the resident before any escrow closes on a resale of the manor.