

Fire Extinguisher Log Sheet for Mutual 56

		White-hall		Edge-water			Lakeshire																	Notes
2025	Initials	1203	1204	1252	1254	1257	1902	1903	1905	1908	1909	1910	1911	1914	1916	1917	1921	1923	1924	1927	1928	1929	1933	
1/4	HA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2/3	HA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3/6	HA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4/7	HA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5/8	HA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6/5	HA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7/4	HA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8/11	HA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

A checkmark indicates:

1. Extinguisher can, hoses, and nozzles are not damaged, dented, or crushed.
2. The pin is securely attached to the handle by the breakaway twist-tie. Reasonable extinguisher access is available.
3. Nothing is blocking the fire extinguisher and it is easily accessible.
4. The extinguisher gauge is in the green.