

Fire Extinguisher Log Sheet for Mutual 56

		White-hall		Edge-water		Lakeshire																	Notes			
2025	Initials	1203	1204	1252	1254	1257	1992	1993	1995	1998	1999	1910	1911	1914	1916	1917	1921	1923	1924	1927	1928	1929		1933	1937	
1/4	HL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
2/3	HL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
3/6	HL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
4/7	HL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
5/8	HL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
6/5	HL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
7/4	HL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
8/11	HL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
4/3/20	HL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	

A checkmark indicates:

1. Extinguisher can, hoses, and nozzles are not damaged, dented, or crushed.
2. The pin is securely attached to the handle by the breakaway twist-tie. Reasonable extinguisher access is available.
3. Nothing is blocking the fire extinguisher and it is easily accessible.
4. The extinguisher gauge is in the green.